

Are all fuses fitted in easily accessible positions

Yes

Are the fuses of standard dimensions

SS. "Swiftlite" & "Albertolite"

It is submitted the Portland & Oregon Surveyors  
be requested to state whether fees for the  
survey of the Electric Installations of  
these vessels have been charged to  
the Shipbuilders & if so the amounts of  
the fees should be stated

See fees  
marked  
reports  
30/1/22  
20/7/21



© 2020

Roll  
Lloyd's Register  
Foundation  
16/7/21

004394-004404-0191

Where are the switches controlling the masthead and side lights placed

wheel house

$$\begin{array}{r} 249 \\ 485 \\ \hline 674 \end{array}$$

$$\begin{array}{r} 192 \\ 498 \\ 63 \\ \hline 1128 \end{array}$$

$$\begin{array}{r} 1058 \\ 138.1 \\ \hline 2429 \end{array}$$

$$\begin{array}{r} .893 \\ .342 \\ .124 \\ .693 \\ \hline 2052 \end{array}$$

$$\begin{array}{r} 78 \\ - 51 \\ \hline 163 \\ \hline 114 \end{array}$$

$$\begin{array}{r} 38 \\ 9 \\ \hline 342 \\ .126 \\ .048 \\ .297 \\ \hline 813 \end{array}$$

$$\begin{array}{r} 24.4 \\ 24.4 \\ 48.8 \\ 86 \\ \hline 134.8 \end{array}$$



© 2020

Lloyd's Register  
Foundation