

M. V. Guiderman

Ref. 2725-2

It is submitted that before this case receives consideration the Rot. Surveyors should be referred to the Secretary's letter E' of 10-5-38 regarding alterations to the pumping arrangements in the forward cofferdam. It is noted from their report on the electrical installation that they have recommended a special condition on the vessel's class, but it is not understood why the necessary alteration was not made before the vessel was completed. They should state if any arrangements have been made for this matter to be dealt with.

L. 744



L. 744  
© 2020/38.

Lloyd's Register  
Foundation

004394-004404-0280