

class is subject to the evaporator not being used until
it and the boiler etc. being specially examined
next day docking.

per Surveyor..... Received from Chief Engineer Surveyor.....
NIKITAS K REPORT AIX Cases No. 4904

of the Chief Engineer Surveyor are desired on this case for the consideration of the Cladding Committee.

ement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and
ing out clearly any exceptional features in connection with the case, so that the Cladding Committee may have all the salient points
in the endorsement."—Extract from Sub-Committee's Report, 24/5/02.)


DAMAGE & WEAR AND TEAR.

O.F. 3, 57

an additional communicating valve
now been fitted on the after lock bulkhead with
extension handle operation from the bridge deck
to complete the Society's requirements for the
O.F. 3, 57 self closing cocks remain to
be fitted to the side tank's drain lines

is submitted the vessel is eligible to remain as classed, with

~~subject~~ as recommended, above and
the notation O.F. 3, 57 when the Society's
requirements have been complied with



© 2021
Lloyd's Register
Foundation

004405-004410-0010