

29. JUN. 1965

Ship's Name ~~SS MS~~ "TOSA BAY"
Gross tons 5,217 Port of Registry Hongkong Port Kobe
Date of build 1-1940 Is there a Rpt. 9? No Rpt. No. 14536
No. of visits 1 First date and Last date 6th June, 1965.
Interim Cert. issued Yes Damage rpt. issued No Last rpt. (H.Q. only) Kob 14123
& copy herewith? B-119274 & copy herewith?
Date of completing rpt. 19-6-65 Surveyed at, if different from Port above Hirohata, Japan
Surveyed afloat Afloat Last date of examination in D.D. -
Has a Load Line Survey been held? No Summer freeboard as verified No

State which additional Rpt. 8 is attached: (~~Cont~~); (PS); (~~DD~~); (EQ); (~~Rig~~)

Survey fees £20-0-0 Damage fee - Expenses £2-8-0
S.A. fee £8-0-0

I have surveyed the above-named ship in accordance with the Rules for Equipments (letter a + 2" SQ.)

Now Done : attend on board and witnesses existing four lengths of chain cables to carry ashore (Refer to Yokohama Certificate Y-24360) and also witnesses and verified four lengths of chain cables to place on board the ship's (Refer to Cardiff Certificate SC-4967).

Separation of Certificates :-

At Owner's request, Certificate Y-24360 separated 2 sheets Y-24360-A and Y-24360-A', one certification for 4 lengths and other for 6 length, and also Certificate SC-4967 separated 2 sheets, one certification for 4 lengths and other 6 lengths.

Endorsements :

Upon completion of certificates, endorsement carried out on Certificate Y-24360-A and MS-118957 as "TOSA BAY" of Hongkong, K. Urayama.

Please see particulars on Rpt.8 (EQ) attached herewith.

The items now surveyed are detailed on this report. All were found or placed in good condition unless otherwise stated. I recommend, therefore, that this ship remain as classed ~~with~~ without fresh record of dry docking, subject to anchor chain cables being ranged out and verified at the next drydocking and also any outstanding conditions of ship's class being dealt with as previously recommended.

(Where conditions of class are recommended to be retained, imposed, amended or deleted, particulars must be stated above and on the interim certificate.)

Date of Committee

WEDNESDAY 14 JUL 1965

Minute

As was, subject

KU/my

Note kept (only)

004405 004410-0103 1/3

Surveyor to Lloyd's Register of Shipping

K. Urayama

ALSO FOR

SPL FOR

TRO

RECORDS

DEPT.

SRL

POSTING

HEADER

CERT

FOR CHAIRMAN
CLASSN. CTTEE

14536

$$a + 2'' S\bar{Q}$$

4 NO CABLES

004405-004410-0103^{2/3}

Note:—Where anchors or chain cables are lost or condemned and renewed or supplied the corresponding test certificates should be cancelled by the Surveyors. Original Certificates issued at Yokohama (15-10-64) and also at Cadiff (9-9-64) returned herewith.

Surveyor to Lloyd's Register of Shipping
K. Uravama.

Rpt. 8 (P.S.) DRY CARGO SHIP

Ship's Name SS/MS "TOSA BAY"

Port KOBE

S.S. () Due

Rpt. No. 14536

In dry dock from

In dry dock to

Examined & conditionExamined & condition

Shell plating

Sternframe

Rudder

Was rudder lifted?

Plating, etc. in way of shell openings

Side scuttles & deadlights

Overbd. scuppers & discharges

F.P. spaces

Chain locker

A.P. spaces

Engine space

Boiler space

Under E. & B.

Coal bunker

Tunnel & well

Cement, asphalt, etc., on btm. shell

Weather decks

* Casings

* Deckhouses

* Superstructures

* Skylights

* Companionways

* Hatchways

* Ventilators

* Air & sounding pipes

Doublers under „ „

Steering arrangements (main)

„ „ (aux)

Windlass

Masts & standing rigging

Hand pumps & suction

W.T. doors

Bulwarks, freeing ports, etc.

EQUIPMENT:

Equipment letter a † 2" SQ.

Fee ltr., if diff. from eqpt. ltr.

Anchors: No. on board

Cables { State if ranged Not ranged

Length on board 270 fthms.

Mean dias. range from Not sized

Rule length 270 fthms Dia. 2" SQ.

Mooring ropes -

Other items:

* These items to include their closing appliances

Where a part Special Survey and, say, Dry Docking Survey are held at the same time, the items for SS should be marked "For SS"

30m,2,64 (MADE AND PRINTED IN ENGLAND)

KU/my



© 2021

Surveyor to Lloyd's Register of Shipping
K. Urayama

004405-004410-0103 3/3