



LLOYD'S REGISTER OF SHIPPING

SAFE DEPOSIT CHAMBERS
McLEOD ROAD

KARACHI

P. O. Box No. 4922
Cablegrams: "Lloydreg", Karachi

Telephone: 30429



Dear Sirs,

s.s. "SAFINA-E-JAMHOORIYAT"

In accordance with your verbal request we give below the text of the Committee's reply to your enquiry:

SAFINAEJAMHOORIYAT REURCAB VIEW AGE SHIP COMMITTEE
UNABLE AGREE FURTHER POSTPONEMENT SPECIAL SURVEY NOW
DESIRED UNLESS ON ARRIVAL AMERICAN PORT VESSEL GENERALLY
EXAMINED AS FAR AS PRACTICABLE INCLUDING HOLDS TWEEN
DECKS SURVEYORS PAYING PARTICULAR ATTENTION POSSIBILITY
GROOVING HEELS OF FRAMES AND WASTAGE OF BILGE SHELL
PLATING AND STRUCTURE IN WAY ALSO WEATHER DECKS AND
HATCHWAY COAMINGS AND HULL SUBJECTS AS SRL STOP GE
MACHINERY REQUIRED AND BOILERS ALSO GENERALLY EXAMINED
UNDER STEAM NOW STOP SPECIAL ATTENTION REQUIRED LP
VALVE AND ROD AT GE UNDERSTOOD BEEN REPAIRED AT PONTA
DELGADA IN MAY STOP PERIODICAL LOADLINE SURVEY REQUIRED
FOR ISSUE LLST VALID UNTIL MID SEPTEMBER 1966 STOP NEW-
YORK SURVEYORS ADVISED

Please let us have your confirmation that the
arrangements are acceptable.

Yours faithfully,

J.F.
(J.F. Crawford)
For The Surveyors

M/s Pan Islamic Steamship Co. Ltd.,
Writers' Chambers,
Dunolly Road,
Karachi.

cc: Secretary,
London.



© 2021

Lloyd's Register
Foundation

004405 004410-016A

REPORT

Handwritten signature

Telephone: 31033

KYRYCHI

MASTOD ROYD
2VAE DBICIL CENHIBEZ

PROBES RECEIVED ON SHIPBOARD

Copyright: 1974-81, Lloyd's
P. O. Box 140, 1033



© 2021
Lloyd's Register
Foundation

