

COPY

LLOYD'S REGISTER OF SHIPPING

71, Fenchurch Street, London, E.C.3

Telegraphic Address { Inland: Committee, London, Telex
Overseas: Committee, London, E.C.3

Telephone: ROYal 9166
Telex No.: 24305

22nd March, 1963.

Dear Sirs,

CLASSING LETTER

C.
DHGK/DET

"SAFINA-E-JAMHOORIYAT". In February the Chittagong Surveyor recommended that the necessary repairs or renewals to all boilers should be dealt with at your Port where the ship was bound, and it is concluded that these boilers are now receiving attention.

I take this opportunity to remind you that the water end valve chest of the after main feed pump required to be renewed by last January and that both centre and inboard main feed pump water ends require to be renewed by the end of next month. Please confirm that the condition of class relating to the water end valve chest of the after main feed pump is now receiving attention.

4,21 "GALLE". As recommended. I have to point out however that you should discontinue the use of the old Rpt. 9.

Yours faithfully,

pro Clerk to the
Classification Committee

The Surveyors,
KARACHI.



© 2021

Lloyd's Register
Foundation

004405-004410-0163