

EA

22 FEB 1965

Ship's name "COPTIC" Port FRE No. 4156

Last survey date 30.1.65.

Class is subject to wasted 2nd deck plating in way of Nos. 2 & 3 hatchways and indented side shell plating in 2nd & 4th strakes below sheer abreast foremast (p & s) and in 3rd strake below sheer abreast mainmast (s.s) being specially examined and dealt with as necessary, next drydocking, and to shell plating 'G' strake (p & s) (between 20' & 24' marks) at the stem bar attachment being specially examined and dealt with as necessary at the S.S. ACTION is DEFERRED for completion of S.S.

S.R.L. Appendix (as before ~~XXXXXX~~)

Surveys due

EXTENDED S.S.(D) case - due 10,64 - commenced
Brs. 5,64. Postponement of completion until
6,65 ~~merits~~ approved. *ed. 28/1/65. G.E. held Lw. 12/64.*

Nature of present survey (afloat ~~and in drydock~~)

Wear and tear repairs.

Is interim certificate in order

Yes/No/None

~~Items outstanding in way for S.S.~~

FOR PORTION OF SURVEY HELD: See List in Ship Reports Dept.

SS proposed to be completed by


Recommendation

SUBMITTED ACTION be DEFERRED for completion of S.S. by 6,65, subject as above.

SUBJECT.

IN S.R.L. APPENDIX

Shell plate No. 5 in 3rd strake below sheerstrake (p.s. from aft) slightly indented.
Indents in tank top plating in way of No. 6 hold, also to shell plating (p & s).
Rudder plate and 2nd arm set over.
(Extended S.S).



© 29/18/2/65

Lloyd's Register

004411-004417-0064