

EA

Ship's name "COPTIC" Port LIV No. 165436
Class is subject to wasted 2nd deck plating in way of Nos. 2 & 3
15.12.64.

hatchways and to indented side shell plating in 2nd & 4th strakes below sheer abreast foremast (p & s) and in 3rd strake below sheer abreast mainmast (s.s) being specially examined and dealt with as necessary next drydocking, and to shell plating 'G' strake (p & s) (between 20' & 24' marks) at the stem bar attachment being specially examined and dealt with as necessary at the Special Survey. (10,64).

S.R.L. Appendix (as before ~~XXXXXXXX~~)

Surveys due EXTENDED S.S.(D) case - due 10,64 - commenced Brs.5,64.

Nature of present survey (afloat ~~XXXXXXXXXXXXXXXXXX~~ and in drydock)

G.E. for postponement of S.S.
Wear and tear repairs.
Examination of S.R.L? & S.R.L.Appendix items.

Is interim certificate in order Yes ~~XXX/XXXX~~

~~XX~~

FOR PORTION OF SURVEY HELD: See List in Ship Reports Dept.

SS proposed to be completed by

NOTED

~~XXXXXXXXXXXXXXXX~~

SUBJECT as above but ACTION be DEFERRED for completion of Special Survey.

SUBJECT

INCS.R.L.APPENDIX

Shell plate No.5 in 3rd strake below sheerstrake (p.s.from aft) slightly indented.
Indents in tank top plating in way of No.6 hold, also in shell plating (p & s).
Rudder plate and 2nd arm set over.
(Extended S.S).

The Surveyors recommend postponement of completion of Special Survey until 6,65 and this merits approval.

P.T.O.

Lloyd's Register Foundation

The Owners should be advised through the Surveyors, it is concluded, that since the requirements of an Extended S.S. have not been complied with in this instance, it is intended to revert the ship to normal survey procedure.

Confirmation will be appreciated.

*Not necessary to visit
final para 1 fwd
ltc 12/1/55*

Examination of S.R.L. & S.R.L. Appendix items.
Wear and tear repairs.
G.E. for postponement of S.S.

FOR PORTION OF SURVEY HELD: See List in Ship Reports Dept.

As proposed to be completed by

NOTED

SUBJECT as above but ACTION be DEFERRED for completion of Special Survey.


SUBJECT

IN S.R.L. APPENDIX

Rudder plate and arm set over.
also in shell plating (p & a).
Indents in tank top plating in way of No. 6 hold.
(p.s. from aft) slightly indented.
Shell plate No. 5 in 3rd strake below sheerstake

The Surveyors recommend postponement of completion of Special Survey until 6/5 and this merits approval.

P.T.O.



© 2020

Lloyd's Register Foundation