

EA

23 SEP 64

Ship's name "COPTIC"

Port

DDN

No.

7002

Last survey date 30.8.64

Class is subject to wasted 2nd deck plating in way of Nos.2 & 3 hatchways and to indented side shell plating in 2nd and 4th strakes below sheer abreast foremast (p & s) and in 3rd strake below sheer abreast main mast (s.s) being specially examined and dealt with as necessary next drydocking.

S.R.L. Appendix (as before or ~~xxxxxx~~)

Surveys due EXTENDED S.S.(D) due 10,64 - commenced Brs.5,64.

Nature of present survey (afloat and ~~xxxxxxxxxxxx~~)

Temporary repairs to leakage.

Is interim certificate in order Yes/No/None

It ~~XXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXX~~

FOR PORTION OF SURVEY HELD: See List in Ship Reports Dept.

Testing of FPT & No.1 DB tank  
RSP 4/11/64

SS proposed to be completed by

Recommendation SUBJECT as above and to shell plating 'G' strake (p & s) (between 20' & 24' marks) at the stem bar attachment being specially examined and dealt with as necessary at the Special Survey.(10.64)

As Now Subject

IN S.R.L.APPENDIX

Shell plate No.5 in 3rd strake below sheerstrake (p.s.from aft) slightly indented.  
Indents in tank top plating in way of No.6 hold, also in shell plating (p & s).  
Rudder plate and 2nd arm set over.  
(Extended S.S).



© 2020

Lloyd's Register Foundation

Handwritten initials and date: 23.9.64

004411-004417-0073