

F. 2271 (SWB)

LLOYD'S REGISTER OF SHIPPING

UNITED WITH THE BRITISH CORPORATION REGISTER

ALTERATIONS TO CONDITIONS OF ASSIGNMENT OF LOADLINES

Ship's Name "SEREMBAN"

Official No. 180423

Port of Registry SINGAPORE.

This ship has been under survey at SINGAPORE.

on 12th April, 1961 ~~1951~~ and the following alterations to the conditions of assignment of loadlines have now been effected ~~found~~—

CREWS TOILET, TWEEN DECK PORT SIDE AFT.

Scupper originally draining to the Engine room bilge now discharging overboard at Tween deck level through two 2" diameter G.M. non return valves on the ship's side, the inner valve being accessible for examination at all times.

Notes
at
10-5-61



A copy of this Report has been placed on board.



© 2020

Lloyd's Register
Foundation

004418-004425-0029