

1

Sent to Chief Surveyors

Received from Chief Surveyors

VESSEL'S NAME

Steel MS. "DUNERA"

Report

Gls.

No. 58752

For the CHIEF SHIP SURVEYOR ~~XXXXXXXXXXXXXXXXXXXX~~

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Nature of Survey

First Entry

When due

--

100AL 'With Freeboard'

3 Dks. Platform deck forward.

Cell. DB 423' 1486t, Tanks at sides of tunnels 620t, FPT 121t, APT 43t.

FK, 9 BH, pt. Cem., Lloyd's A &amp; CP.


Shade Dk. F 61'

O.L. 516' 10" (.6)

The Certificate of Classification to be endorsed "Cargo battens not fitted" and the same notation to be printed in the Register book.

*John*  
2-9-37

*This is generally a sister ship to the "DILWARA"*



© 2021

Lloyd's Register  
Foundation