

Rpt. 8.

(Received at London Office)

No.

117665 A.

## REPORT OF SURVEY FOR REPAIRS, &amp;c.

Date of writing Report 19

When handed in at Local Office 19

Port of

LONDON

No. in  
Reg. Book.

Survey held at

Date, First Survey

Last Survey

19

52114 on the Wood, Iron or Steel M/S "ATLANTIC"

TONNAGE :-

Built at

Newcastle

By whom

Armstrong Whitworth

When

1925-8

GROSS

7342

Owners

A/R Seljan

Owners' Address

(If not already recorded in Appendix to Register Book)

UNDER DK.

672

Managers

Paul Jensen

Port belonging to

Bergen

NET

4

Surveyed Afloat or in Dry Dock?

Name of Dock

Destined Voyage

Cell/Dor/Dba

feet; u&amp;B

feet; f

fee

total capacity

tons, FPT

tons; APT

tons; MT

feet tons.

Only alterations in the existing records of tanks should be inserted.

I.B. All alterations in the existing records should be underlined.

t Report, No.

5464

Port

Bdx

Surveys, when held, must be reported in detail and verbatim in the terms of the Rules and items remaining to complete Surveys should be summarised. State clearly the cause of Repairs, if any, and, in detail, the nature and extent of Examinations subsequent repairs. Repairs on account of Damage (the cause of which must be stated) should be separated from Repairs due to other causes; and besides being detailed in the body of the report, should be summarised in the form shown below. Whenever the movement of Anchors or Chains is reported the particulars should be clearly stated in the space provided on the back of this form. Also the dates and initials of any letters respecting this case.

Where cases where the Surveyor has not made a special damage report he is required to state whether he offered his services for this purpose and to whom and why they were declined

Was a damage report made by anyone else? if so, by whom?

AIRS, OR EXAMINATION AS PER RULE, FOR

Society's Freeboard (if assigned, as painted on Ship and now verified)

ft.

ins.

CONTINUOUS SURVEY

WRECK  
SECTION

No. 918

Summary of Damage Repairs :-	Shell Plates.	Frames.	R. Frames.	Floors and Bracket Floors	Beams.	Inner Bottom Plates.	Dk. Plates.	Other Items :-
Renewed ...								
Removed and Fair'd or Repaired								
Fair'd or Repaired in place ...								

## GENERAL CONDITION OF THE

Condition of Decks	Bulkheads	Engine Room Skylights	Copper, or Y.M.
Condition of Plating	Ceiling	Coal Bunkers, Openings, Covers, &c.	(State if on Felt.)
Condition of Fastenings	Cement or Asphalt	Oil Bunkers	When fitted, Month Year
Condition of Plating in way of sidelights	Rudder	Scuppers	Boats
Condition of Frames	Steering gear and its connections	Cargo Hatchways	Masts, Yards, &c.
Condition of Studding	Windlass	Hatches	Condition, how ascertained
Condition of Sides	Have pumps been examined and found efficient?	Planking	(State if wedges removed.)
Condition of Bottom	Have Stulce Valves been examined and found efficient?	Caulking	Equipment letter
Condition of Tanks	Have Watertight Doors been examined and found efficient?	Treenails	Anchors. No. of
Condition of Tanks tested?	Have Ventilators and their Coamings been examined and found efficient?	Breasthooks & Stemson	Cables (State if now ranged)
	Have Watertight Doors been examined and found efficient?	Transoms, Pointers & Crutches	" length mean diamr.
	Have Watertight Doors been examined and found efficient?	Timbers of Frame at openings	(on board.)
	Have Watertight Doors been examined and found efficient?	" " at other places	" Rule length size
	Have Watertight Doors been examined and found efficient?	Stringers, Clamps & Shelves	Chain Locker
	Have Watertight Doors been examined and found efficient?	Salting	Hawsers & Warps
	Have Watertight Doors been examined and found efficient?	State if examined.	Standing and Running Rigging
	Have Watertight Doors been examined and found efficient?		Sails

## General Observations, Opinion as to Class, Recommendation, &amp;c. :-

State clearly whether any and, if so, what alteration is suggested to be made in the existing classification and notification of the vessel in the Register Book consequent upon this survey, thus, for example :- "to remain as classed in the Register Book without fresh record of Survey," "to remain as classed and to have record of survey, 1,38," or "to remain as classed and to have record of survey, 1,38, and the notations of ss No. 1-38."

Survey Fee (per Section 29)	£	:	:	Fees applied for,
Special Damage or Repair Fee (if any) (per Sec. 29)	£	:	:	10
Travelling Expenses (if chargeable)	£	:	:	Received by me,
Second Surveyor's Fee (if any)	£	:	:	10

Committee's Minute

FRI. 4 AUG 1950

Character Assigned

Decide BS. class

NV

Surveyor to Lloyd's Register of Shipping

General Committee

Thursday, 14th September 1950

Classing Committee's decision

© 2021

Lloyd's Register

Foundation

004440-004449-0173