

replacement of Anchors or Chains is reported the particulars should be clearly stated in the space provided on the back of this form. State also the dates and initials of any letters respecting this case.

SC 706 - 5/49  
AS 9/5 3/52

BC

m.10.47.

ent to Chief Surveyors.....

Received from Chief Surveyors 29 MAY 1952

VESSEL'S NAME 'CHARLES WHYTOCK' REPORT Lon. No 123247

For the CHIEF SHIP SURVEYOR ~~and CHIEF ENGINEER SURVEYOR.~~

In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—(Extract from Sub-Committee's Report, 24/5/52.)

dup 2.52

ature of Survey..... When due.....

This ship is classed BS\* (Whaler, with Freeboard).

SPECIAL SURVEY TYPE 4 becomes due 5,53.

Notation of 'A.S.2,51' is assigned.

The class is subject to stream anchor on board (supplied Drb. 3,52) being submitted to the Statutory Test at the earliest opportunity.

The DURBAN Surveyors in letter dated 30.4.52 state "The Owners (The Union Whaling Company, Ltd) have informed us that they have decided to withdraw the above vessel from Classification with the Society"

IT IS THEREFORE SUBMITTED the ship's class be withdrawn from the Register Book and (BS\*-Class Withdrawn) inserted in lieu, indicating withdrawal at Owners' request.

WITHDRAW CLASS and  
INSERT IN R.B.

(BS\* - Class Withdrawn)

20.  
2.4.  
BM.  
22.5.52.



© 2021

Lloyd's Register  
Foundation

004440-004449-0181

Character Assigned

12<sup>th</sup> June 1952  
Classing Committee's