

- 8. FEB. 1967

Ship's Name ~~SEMS~~ " OAKMORE "

Port Liverpool

Processing  
Number: LR 525980

Gross tons 4700

Rpt. No.

16 9 9 17

Port of Registry Liverpool

Date of  
build 1939

Is there a Rpt. 9?

No

No. of visits 2.

First date 17.1.67.

Last date 18.1.67.

Cert. B issued  
& copy herewith? Yes.Damage rpt. issued  
& copy herewith? -

Last rpt. (H.Q. only)

LIV. 169273.

Date of  
completing rpt. 18.1.67.

Surveyed at, if different from Port above

-

Safcon Cert. (ST)  
issued & copy herewith?

If surveyed in D.D. last date of examination

-

Has a Load Line  
Survey been held? No.

Summer freeboard as verified

-

State which additional Rpt. 8 is attached: (Cont); (A); (DR); (EQ); (Rig)

Survey fees

Damage fee

Expenses

Rpm £12.

15/-

ny.

20

S.A. fee

I have surveyed the above-named ship in accordance with the Rules for

Repairs

Now Done:- Welded doubler fitted to No. 2 Tank top starboard side in line with middle of hatchway, in way of local corrosion.

S.R. List No. 26B:- Nil.

S.R.L. Appendix No. 18:- Nil.

I declare that the items detailed in this report (except as stated otherwise) comply with the requirements of the Merchant Shipping (Cargo Ship Construction and Survey) Rules 1965, applicable to this ship, and are in all respects satisfactory for the service on which the ship is intended to ply namely International voyages/voyages within the limits

(The above declaration applies only to sea-going cargo ships of 500 tons gross and above registered in the U.K.)

The items now surveyed are detailed on this report. All were found or placed in good condition unless otherwise stated.

I recommend, therefore, that this ship remain as classed ~~XX~~/without fresh record of dry docking. subject to any outstanding

condition of class being dealt with as previously recommended.

(Where conditions of class are recommended to be retained, imposed, amended or deleted, particulars must be stated above and on the interim certificate.)

Date of Committee

LIVERPOOL 7 FEB 1967

H.B. McQueen.

Minute

Deferred for 55.

H.B. McQueen  
Surveyor to Lloyd's Register of Shipping

ALSO FOR

SPL FOR

TRO

SRL

POSTING

HEADER

CERT

Lloyd's Register  
Foundation

004466-04476-0233