


LLOYD'S REGISTER OF SHIPPING

Port LiverpoolDate 26th January, 1966.

This is to Certify *that I have surveyed part of the machinery*
of the **m.v. "OAKMORE",** **4700 gross tons** *of Liverpool*
for Docking and Condition of Class whilst the vessel lay in drydock at
 Liverpool on the 7th January, 1966,

and that all my recommendations have been carried out to my satisfaction. I
am reporting accordingly and recommending to the Committee of Lloyd's Register
of Shipping that the machinery classification should be retained ~~and the following~~

~~survey records assigned~~ without condition of class regarding the Port Forward
 Auxiliary engine entablature, and subject to the Starbd. forward auxiliary
 engine No. 6 unit entablature (Metalocked 3,65) being specially examined by
 January, 1967 (12 months) and to any other outstanding conditions of class
 being dealt with as previously recommended.

Parts now examined:—

Propeller, underwater fastenings and sea valves.

Huber
 Surveyor to Lloyd's Register of Shipping

A. Jackson.

ABS Auxiliary Boiler Survey
 CSM Continuous Survey of Machinery
 DBS Donkey Boiler Survey
 ES Engine Special Survey

MBS Main Boiler Survey
 OF Fitted for oil fuel (date) FP above 150° F.
 SGS Steam Generator Survey
 SPS Steampipe Survey

TS Tailshaft Survey
 TS(CL) Tailshaft Survey—Continuous Liner
 TSN Tailshaft renewed
 TS(OG) Tailshaft Survey—Oil Gland

This Certificate is issued upon the terms of the Rules and Regulations of the Society, which provide that:—

"The Committees of the Society use their best endeavours to ensure that the functions of the Society are properly executed, but it is to be understood that neither the Society nor any Member of any of its Committees nor any of its Officers, Servants or Surveyors is under any circumstances whatever to be held responsible or liable for any inaccuracy in any report or certificate issued by the Society or its Surveyors, or in any entry in the Register Book or other publication of the Society, or for any act or omission, default or negligence of any of its Committees or any Member thereof, or of the Surveyors, or other Officers, Servants or Agents of the Society"