

Ship's name OAKMORE
SPR appendix NIL.

Port LIV.

No. 166601

Class is subject to

th 29.5.65 + Last survey date 8.6.65

- 1 Port aft aux engine NO1 unit entablature & crankcase (metablocked 11.64) being examined by 9.65 (6 mos limit)
- 2 Starboard forward aux engine NO6 unit entablature (metablocked 3.65) being examined by 9.65 (6 mos limit)

CS(M) advanced.

Port Forward aux engine entablature found fractured in way of Nos. 2 & 3 and Nos 3 to 4 cylinders, now repaired by metablock & recommended repairs being specially examined by end of 12.65.

Fire & Bilge Pump casing found wanted & now recommended casing being specially examined and dealt with as necessary by 6.66 (12 mos)

SPR item NO2 above:- Repair found leaking & now restitched & tested & found satisfactory meantime but recommended the metablock repair being specially examined by 12.65.

It is submitted that this vessel is eligible to remain as **CLASSED**.

Subject as above for item NO1 and as amended for item NO2 and subject as now recommended for Port Forward aux engine entablature & for Fire & Bilge Pump casing.

For CS(M)
See Form TE.

004466-004476-0282

29.7.65

Lloyd's Register
Foundation