


## LLOYD'S REGISTER OF SHIPPING



Port.....Liverpool.....

Date.....29th June, 1965.....

This is to Certify that <sup>we</sup> I have surveyed part of the machinery  
of the m.s. "OAKMORE", 4700 gross tons of Liverpool

for Advancement of Continuous Machinery Survey, Condition of Class,  
(Starboard forward generator engine entablature "Metalock" repair),  
Repairs (port forward generator engine entablature),

and that all <sup>our</sup> ~~my~~ recommendations have been carried out to <sup>our</sup> ~~my~~ satisfaction. <sup>We</sup> ~~I~~  
are  
~~am~~ reporting accordingly and recommending to the Committee of Lloyd's Register  
of Shipping that the machinery classification should be retained ~~and the following~~

survey records assigned subject to fire and bilge pump casing being specially  
examined and dealt with as necessary by 6,66 (12 months' limit), also subject  
to "Metalock" repairs to starboard forward generator entablature in way of  
No. 1 cylinder and port forward generator entablature in way of Nos. 2 to 3 and  
Nos. 3 to 4 cylinders being specially examined by 12,65, also subject to any  
outstanding conditions of class being dealt with as previously recommended.

Parts now examined:—

Fire and bilge pump.  
Inboard independent air compressor, coolers and safety  
devices.

*F. E. Higgins*

Surveyor to Lloyd's Register of Shipping  
F. E. Higgins (for D. Hague, H. M. Pollock  
& self).

ABS Auxiliary Boiler Survey  
CSM Continuous Survey of Machinery  
DBS Donkey Boiler Survey  
ES Engine Special Survey

MBS Main Boiler Survey  
OF Fitted for oil fuel (date) FP above 150° F.  
SGS Steam Generator Survey  
SPS Steampipe Survey

TS Tailshaft Survey  
TS(CL) Tailshaft Survey—Continuous Liner  
TSN Tailshaft renewed  
TS(OG) Tailshaft Survey—Oil Gland

This Certificate is issued upon the terms of the Rules and Regulations of the Society, which provide that:—

"While the Committees of the Society use their best endeavours to ensure that the functions of the Society are properly executed, it is to be understood that neither the Society nor any Member of any of its Committees is under any circumstances whatever to be held responsible for any inaccuracy in any report or certificate issued by the Society or its Surveyors, or in any entry in the Register Book or other publication of the Society, or for any error of judgment, default or negligence of any of its Committees or any Member thereof, or the Surveyors, or other Officers or Agents of the Society."