

COPY

# LLOYD'S REGISTER OF SHIPPING

71, Fenchurch Street, London, E.C.3

Telegraphic Address { Inland: Committee, London, Telex  
Overseas: Committee London, E.C.3

Telephone: ROYal 9166  
Telex No.: 24305

9th April, 1965.

Dear Sirs,

C.  
MWK/DET

## S.S. "AL HUSAINI"

The Hamburg Surveyors have reported that this ship was examined in drydock during January and, at that time, the Engine Survey was completed and, in the circumstances, notations of Special Survey 9,63, Engine Survey 1,65 and Docking Survey 1,65 have been assigned by the Committee.

The class has now been continued subject to the spare bower anchor being verified with certificates, and 30 fathoms of chain cable being supplied at the earliest opportunity, also to indented shell plating in first and second strakes below sheerstrake (starboard side) in way of aft end of No.1 'tween deck being specially examined and dealt with as necessary at the next drydocking, and to wasted rudder trunk plating being specially examined and dealt with as necessary before the end of the present month.

It was stated that the latter item would receive attention on the ship's arrival at Karachi and it is concluded the Owners will make the necessary arrangements for this matter to be dealt with.

I would also take this opportunity to point out that the Main Boiler Survey became due at the end of last month and I shall be glad to learn when the Owners propose to carry out this survey.

Yours faithfully,

The Surveyors,  
KARACHI.

PRO Clerk to the  
Classification Committee

Lloyd's Register  
Foundation

2064770004480-0355