

BLUE MARLIN

WRECKED

WRECK
SECTION
No. 1038

J	J
F	F
M	M
A	A

M	M
JE	JE
JY	JY
A	A
S	S
O	O
N	N
D	D



© 2020

Lloyd's Register
Foundation

004486-004488-0013

SAFCON CASE
CERT ISSUED.....

When H. limit

501970 BLUE MARLIN 7126 100A1 SS 7/65 1944-8 Burrard D.D. Co. Ltd.—Vcr S CSD T 3Cy. 24½" 37" & 70" x 48"
HOZY exAnthony-64 exGulfside-51 4430 441' 6" 57' 2" 27' 8½" 2500ihp 940t (o.f.)
exFort Alabama-47 10768 LMC 417' 9" 56' 11" 37' 4" Canadian Allis-Chalmers Ltd. Mtl
Df Esd Blue Shark Steamship Co. 2 dks 2WTB 250lb Spt 230lb hs(10233) 10k
Gc Rdr S.A. MN(628) EL at 2¼" SQ RW 7BH 13W Der 1(30) 10(5) NB (p) made 43 fitted 64

NOTES *Liberty Tyne Shaft* *all correspondence to Overseas Steamships Co Manila see ltr 26/2* *Care to American HKG Address 70, Southsea Investment Company 17 Connaught Rd. West, 2nd floor GPO Box 424 HKG* SPL NOTES S.R.L. (MARCY)

LAST SPECIAL SURVEY	HULL	5.65	7.65	MCHY.	ES	7.65													
LAST DOCKING SURVEY		6.65	12.65																
ANNUAL SURVEY																			
BOILER		7.65	12.65																
AUX / DONKEY BLR																			
STM. GEN.																			
SCREWSHAFT	CL	N	7.63	11.65															
STEAMPIPES			7.65																
WEAR DOWN ON STERN BUSH			12.4"	0.170"															
FIRE EQUIPMENT SURVEY DUE			1/68																

T3 (N) 7.63-2 cracks hog way with minor prop damage No other defects to S3.

A/R memo 5/4

M LIMIT

A/R LTR 21/3

