

Lloyd's Register of Shipping.

7TH FLOOR, SHINKO BUILDING,
8, KAIGAN-DORI, IKUTA-KU,
(KOBE PORT P. O. BOX NO. 446)
KOBE.

3-360

13th March, 1967.

Your Ref:

Our Ref:

Dear Sir,


S.S. "BLUE MARLIN"
Kobe Report No.17452

Referring to our above report, the Starboard Main Boiler forward water gauge cock was found choked at the water end and it is considered the damage now reported was caused through shortage of water. The aft gauge cock was out of order.

The Port Main Boiler water gauges were tested and found in order.

The Owners have now directed the ship to Formosa where it is understood she will be sold for scrap.

Yours faithfully,


For the Surveyors

The Secretary,
LONDON.

YK/rm



© 2020

Lloyd's Register
Foundation