

COPY OF AIR LETTER

LLOYD'S REGISTER OF SHIPPING

71, Fenchurch Street, London, E.C.3

Your Ref:2740/66

Our Ref:R.SEI/BN

12th September, 1966

Dear Sirs,

S.S. "BLUE MARLIN"

With reference to your letter of the 30th August, I have to inform you that the Committee have noted your proposal to carry out the overdue Liberty-Type Screwshaft Survey when the vessel is drydocked at Hong Kong on the 20th/25th September.

The following survey matters should also be dealt with at the forthcoming drydocking:-

(1) Expired machinery subject requiring that the windlass cylinder block (Metalocked September 1964 be re-examined by the end of July 1966.

(2) Main Boiler Survey due July 1966.

The class of the vessel is also at present continued subject to the midship deep tanks (port and starboard) not being used as such until tested.

Yours faithfully,

cc H.K.G.
cc MANILA

Deputy Classification Manager,

The Overseas Steamship Co. Inc.,
4th Floor
Filipinas Building
Plaza Moraga,
P.O.Box 3481,
Manila
PHILIPPINES.

Cash to Ocean H.K.G. Office

O.S.C. Inc.

*40 Southern Investment Company
17 Connaught Rd West, 2nd Floor*

*GPO Box No 424
H.K.G.*

© 2020

Lloyd's Register
Foundation

004686-004488-0044