

52/1986

Ship's Name SS/MS "BLUE MARLIN" LR 501970

Gross tons 7126 Port of Registry Panama Port Yokohama

Date of build 1944-8 Is there a Rpt. 9? No Rpt. No. 6375

No. of visits 1 First date & Last date 30-12-65

Interim Cert. issued & copy herewith? Yes Damage rpt. issued & copy herewith? - Last rpt. (H.Q. only) TP 65222

Date of completing rpt. 3-1-66 Surveyed at, if different from Port above Chiba

Surveyed afloat and/or in D.D. Afloat Last date of examination in D.D. -

Has a Load Line Survey been held? No Summer freeboard as verified -

State which additional Rpt. 8 is attached: (Cont); (PS); (DR); (EQ); (Rig)

Survey fees Damage fee - Expenses ¥ 2,500.-

Part SS ¥ 15,000.-

S.A. fee -

I have surveyed the above-named ship in accordance with the Rules for Part SS and Condition of Class survey.

Now Done

Part SS :

105 fathoms chain cable now renewed.

To Complete SS :

Deep tanks (P & S) to be tested.

Condition of Class (SRL No.245):

105 fms.(used stud link chain cables)now renewed. After fitted chain cables the windlass examined under working condition and found satisfactory. It is submitted that this item no longer constitutes a condition of class and be deleted from SRL.

Note :

The Master stated that the deep tank survey will be held at Hong Kong to which port the vessel is now proceeding direct.

The items now surveyed are detailed on this report. All were found or placed in good condition unless otherwise stated. I recommend, therefore, that this ship remain as classed with/without fresh record of dry docking notation of SS with date when the survey has been completed, subject to any outstanding condition of class being dealt with as previously recommended but without condition of class regarding 105 fms. chain cable.

(Where conditions of class are recommended to be retained, imposed, amended or deleted, particulars must be stated above and on the interim certificate.)

Date of Committee

Minute

THURSDAY 17 FEB 1966

See H49 19952

[Signature]
 H. TERASHIMA
 Surveyor to Lloyd's Register of Shipping

ALSO FOR

SPL FOR

TRO
mal

SRL

POSTING

HEADER

CERT

Lloyd's Register Foundation

004486-004488-0062 1/2

action taken or recommended should be described fully under "defects & repairs". When any part has been subjected to pressure test this should be stated.

date of the next Special Survey. Where repairs have been effected or it is considered that re-examination or repairs should be made before that date the circumstances and

The condition of any item is to be described as "good" only when it has been examined, found or placed in good condition and is considered to be acceptable until the due

3 FEB 1966

