

11 OCT 1965

SHIP'S NAME "BLUE MARLIN"

PORT TPI

No. 65222

:-

LAST SURVEY DATE


11.7.65.

CLASS IS SUBJECT TO :-

1. Windlass cylinder block (M.L. 9.64) being re-examined by 5.65 (8 months).
2. ∇ Main condenser water box division plate to be specially examined and dealt with by end of 5.65.
3. ∇ Port inboard bilge and G.S. pump water end cylinders be specially examined and dealt with as necessary by 5.65.

Docking . WD .124"
 MBS due 8.65 now held
 ES commenced 9.6.65 now held
 SRL item 1 above examined surveyor
 recommends be re-examined by 7.66
 SRL items 2 & 3 above dealt with
 SPS now held

It is submitted that this
 vessel is eligible for THE
 RECORD. ES 7.65, MBS 7.65 & SPS 7.65
 subject to item 1 above amended without
 subject to items 2 & 3 above.



5/10/65

P.T.O.

0088 1/2

(2)

11 OCT 1965

SHIP'S NAME

Blue Marlin

PORT

No.

LAST SURVEY DATE

CLASS IS SUBJECT TO

It is concluded that surveyor should
confirm that copper steam pipes
were annealed as required by
Chapter 6 Section 1006 of the Rules.



© 2020

Lloyd's Register
Foundation