

COPY

LLOYD'S REGISTER OF SHIPPING

No. 65222



Port SAIPSI

Date 12th July 1965

This is to Certify that I have surveyed part of the machinery
of the S.S. "BLUE MARLIN" 7,126 gross tons of Panama
for DS, ES, MBS, SPS & Condition of Class whilst the ship lay afloat and
in drydock at Keelung on the 9th June, 1965 and subsequently
and that all my recommendations have been carried out to my satisfaction. I
am reporting accordingly and recommending to the Committee of Lloyd's Register
of Shipping that the machinery classification should be retained and the following
survey records assigned ES, 7,65; MBS 7,65 & SPS 7,65 subject to windlass
cylinder block (Metalocked 9/64) being specially examined by 7/66 (12 mos.)
but without conditions regarding main condenser water box division plate,
P.S. inboard bilge & outboard general service pumps.

Parts now examined:—

Propeller, end of sternbush, sea connections & outside fastenings.
Main boilers (2) with its safety valves adjusted & oil fuel installation.

Main Engine :

All cylinders, covers, pistons, rod, valves & gears.
All connecting rods, top ends & guides.
All crankpins & bearings.
All journals and bearings.
Stop & manoeuvring valves.
Main engine driven pump.
Thrust blocks, shaft & bearings.
Intermediate shafts & bearings.
Main & auxl. condensers.
Forced draught fan.
Holding down bolts & chocks.

(P.T.O.)

Henry S. M. Tan
Acting Surveyor to Lloyd's Register of Shipping
Henry S. M. Tan

KEY TO ABBREVIATIONS

ABS	Auxiliary Boiler Survey	MBS	Main Boiler Survey	TS	Tailshaft Survey
CSM	Continuous Survey of Machinery	OF	Fitted for oil fuel (date) FP above 150° F.	TS(CL)	Tailshaft Survey—Continuous Liner
DBS	Donkey Boiler Survey	SGS	Steam Generator Survey	TSN	Tailshaft renewed
ES	Engine Special Survey	SPS	Steampipe Survey	TS(OG)	Tailshaft Survey—Off Gland

This Certificate is issued upon the terms of the Rules and Regulations of the Society, which provide that:—
"Whilst the Committees of the Society use their best endeavours to ensure that the functions of the Society are properly executed, it is to be understood that neither the Society nor any Member of any of its Committees is under any circumstances whatever to be held responsible for any inaccuracy in any report or certificate issued by the Society or its Surveyors, or in any entry in the Register Book or other publication of the Society, or for any error of judgment, default or negligence of any of its Committees or any Member thereof, or the Surveyors, or other Officers or Agents of the Society."

