

Ship's name

Blue Marlin

Port

Suez

No. 4004

Class is subject to

Last survey date 7.12.65

① Windlass cylinder block (ML 9.6v) being
maxammed by 5.65 (8 mos).
② No 3 inboard generator engine & governor being placed in
good order by end of 5.65 (8 mos). *Done*

ES due 5.6v comm 9.6v not advanced.

Main circulating pump steam cylinder cover broken
piston rod buckled and crosshead damaged.
All satisfactorily renewed or repaired.

It is submitted that this
vessel is eligible to remain
as CLASSED, subject as above.

To complete ES. Pumping engts & Erap sv's to adjust