

LDN SWBD P3

24305 COMMITTEELDN MANILA 3300 PSE A/B PHILMERSHIP MANILA

MOM

PHILMERSHIP3300
COMMITTEE LDNTKU

TELEX OUT

PHILMERSHIP3300

COMMITTEE LDN

PHILMERSHIP MANILA

3/4/64 1550

3 APR 1964

NO.556

BLUE MARLIN EX ANTHONY REURCAB REPLACEMENT BOILER EX DAVID B
HENDERSON COULD BE ACCEPTED IN THIS INSTANCE PROVIDED IT IS OPENED
OUT FOUND OR PLACED IN GOOD CONDITION THE SCANTLINGS OF THE BOILER
TO BE VERIFIED AS FAR PRACTICABLE AGAINST DETAILS SHOWN ON PLANS
NOW FORWARDED TO SAN FRANCISCO SURVEYOR AND MOUNTINGS TO BE IN
ACCORDANCE WITH RULE REQUIREMENTS STOP SAN FRANCISCO BEING
ADVISED REGARDING SURVEY BOILER BEFORE SHIPMENT = COMMITTEE +

CT B +++

PHILMERSHIP33008%

@8).34'E80 .-,)- '2300 4+XV

SORRY PSE RPT

DE PHILMERSHIP MANILA SWELL RCVD BY/MT AT 2300HRS
PASSING N ON TKS BIBI
COMMITTEE LDN

TKU VM BI BI



© 2020

APRIL 3RD/64

Lloyd's Register
Foundation

4486-004488-0161

blissing



© 2020

Lloyd's Register
Foundation