

CABLE IN

31 MAR 1964

COMMITTEE LDN
OSEAGRAM 20 LN
TX0853 GWB3914 PMU1931 TL996 PSS315 GBLX CO PHMA 055
MANILA 55/53 28 1501 VIA IMPERIAL


RECEIVED

31 MAR 1964

LLOYDS REGISTER LONDON ENGLAND

SS **BLUE MARLIN ** EX SS ANTHONY * EN ROUTE BRISBANE AUSTRALIA
DAMAGED PORT BOILER PLEASE ADVISE IF ACCEPTABLE INSTALL SIMILAR
REPLACEMENT BOILER EX SS *DAVID B HENDERSON * BUILT 1943 BY
COMBUSTION ENGINEERING NEW YORK USCG/ABC RULES SUBJECT LLOYDS
SURVEY/CLASSF E E E LLOYDS SURVEY/CLASSIFICATION SAN FRANCISCO
PRIOR SHIPMENT AUSTRALIA AND INSTALLATION TO LLOYDS REQUIREMENTS
PHILMERSHIP +

COL SS **BLUE MARLIN ** EX SS *ANTHONY * SS *DAVID B HENDERSON*
1943 +
SENT 1214/28 RGF
COMMITTEE LDN
OSEAGRAM 20 LN



Lloyd's Register
Foundation

004486-004488-0163

REPORTS

ENG.

11/16



© 2020

Lloyd's Register
Foundation