

COPY
LLOYD'S REGISTER OF SHIPPING

Report No. 288



Port COCHIN.

Date 31st January, 1966.

This is to certify that I have surveyed part of the machinery of the S.S. "APJ AMBAR," 5449 gross tons of Calcutta for advancement of MBS, for damage to Inboard & Outboard Generator Engines and for condition of class to Main Condenser Circulating Water Pump while the vessel lay afloat at Cochin on the 23rd January, 1966 and subsequently.

and that all my recommendations have been carried out to my satisfaction. I am reporting accordingly and recommending to the Committee of Lloyd's Register of Shipping that the machinery classification should be retained and the following survey records assigned "MBS (with date) upon completion," to condition of class on Main Condenser Circulating Water Pump (certificate of the 17th January, 1966 issued at Mormugao) being deleted and to all conditions of class being dealt with as previously recommended.

Parts now examined :—

For MBS: Centre Boiler in its entirety and the Safety Valves of Centre and Port Boilers adjusted under steam.

For Damage Repairs: Inboard & Outboard Generator Engines.

For Condition of Class: Main Condenser Circulating Water Pump.

To complete the boiler survey the Starboard Boiler remains to be examined in its entirety, its safety valves to be adjusted under steam and the oil burning system and remote controls to be examined and tested.

(P. L. DIABREO.)

Surveyor to Lloyd's Register of Shipping

KEY TO ABBREVIATIONS

ABS	Auxiliary Boiler Survey	MBS	Main Boiler Survey	TS	Tailshaft Survey
CSM	Continuous Survey of Machinery	OF	Fitted for oil fuel (date) FP above 150°F.	TS(CL)	Tailshaft Survey—Continuous Liner
DBS	Donkey Boiler Survey	SGS	Steam Generator Survey	TSN	Tailshaft renewed
ES	Engine Special Survey	SPS	Steampipe Survey	TS(OG)	Tailshaft Survey—Oil Gland

This Certificate is issued upon the terms of the Rules and Regulations of the Society, which provide that :—
"While the Committees of the Society use their best endeavours to ensure that the functions of the Society are properly executed, it is to be understood that neither the Society nor any Member of any of its Committees is under any circumstances whatever to be held responsible for any inaccuracy in any report or certificate issued by the Society or its Surveyors, or in any entry in the Register Book or other publication of the Society, or for any error of judgment, default or negligence of any of its Committees or any Member thereof, or the Surveyors, or other Officers or Agents of the Society."

Cert. B. 1

City Press, Calcutta.

2020
Lloyd's Register
Foundation
004486-004488-0338