

PT

~~COCHIN~~

Ship's name

"APJ AMBAR"

Port

COCHIN

No.

257

Class is subject to

Last survey date

19.11.65.

Bower anchor and 15 fathoms of chain cable being supplied at the earliest opportunity,.

ACTION is DEFERRED for examination in drydock after grounding.

S.R.L. Appendix (as before ~~xxxxxxx~~)

Nature of present survey (afloat and ~~in drydock~~)

Examination afloat due to reported fire in No.4 hold.

Recommendation

SUBMITTED ACTION continue to be DEFERRED for examination in drydock after grounding, SUBJECT. subject as above and to No.4 hold being specially examined for fire damage on ship's arrival at Bombay IN S.R.L. Drydocking(grounding). [or Calcutta from present voyage.

IN S.R.L. APPENDIX
Indented shell plating in way of Oil
fuel bunker (p.s).
Shell plate (p.s.amids) pitted.

