

INDEX  
 ENDEAVOR

WRECK  
 SECTION  
 No. 923

J	J
F	F
M	M
A	A

WRECKED

M	M
JE	JE
JY	JY
A	A
S	S
O	O
N	N
D	D



© 2020

Lloyd's Register  
 Foundation

004489-004495-0165



516027	<b>INDIAN ENDEAVOUR</b>	7306	<del>100A1</del>	SS 7/62	1945-8	Short Bros. Ltd.—Sld	S	T 3Cy. 24½" 39" & 70" x 48"	
VWYZ	exEmpire Dominica-46	4601	with freeboard		447' 10" 56' 4" 28' 9"			2500ihp	(o.f)
180162	India S.S. Co. Ltd.	10180	<del>LMC</del>		425' 0" 56' 0" 38' 1"		G.502116 B.464534	Duncan Stewart & Co. Ltd.	Gls
Df Esd	Calcutta	Indian		EL at 2" SQ	F38' 2 dks			3 SB 220½ Spt hs(7248) 9cf	11k
Gc Rdr			MN(510)		RW 7BH		10W Der 1(50)		
RT					WB2279t incl. Tunnel tanks 320t				

NOTES

LAST SPECIAL SURVEY	HULL	1158	762					MCHY.	1258	762									
LAST DOCKING SURVEY		762	83	11-64	10.65														
" BOILER "		762	765	10-64	9.65														
" AUX/DONKEY BLR "		/	/	/	/														
" STM. GEN. "		/	/	/	/														
" SCREWSHAFT "	CL	561	665	11-64															
" STEAMPIPES "		1258	10.64																
" WEAR DOWN ON STERN BUSH "	1 11/8	3/16 before	Revised	0.030"	7 11/64														
Five Equipment Survey due.		13/5/67																	

await wreck report;



© 2020

Lloyd's Register  
Foundation