

2 MAR 1966

Ship's Name SS/~~MS~~ "INDIAN ENDEAVOUR" LR 516029

Gross tons 7306

Port of Registry Calcutta

Port Liverpool

Date of build 8.45

Is there a Rpt. 9? No

Rpt. No. 167909

No. of visits 2

First date 4.2.66.

Last date 11.2.66.

Interim Cert. issued &amp; copy herewith? Yes

Damage rpt. issued &amp; copy herewith? No

Last rpt. (H.Q. only) BOM 16855-

Date of completing rpt. 14.2.66.

Surveyed at, if different from Port above -

Surveyed afloat and/or in D.D. Afloat

Last date of examination in D.D. -

Has a Load Line Survey been held? Yes

Summer freeboard as verified -

State which additional Rpt. 8 is attached: ~~XXXXXX~~; (EQ); ~~XXXX~~

Survey fees

Damage fee

Expenses

£15

12/-

S.A. fee

81

I have surveyed the above-named ship in accordance with the Rules for Condition of Class.

"subject to 255 fathoms of anchor cable being supplied at the earliest opportunity" from Calcutta 3.11.65.

Now Done.

255 fathoms of condemned cable removed ashore and 255 fathoms of new cable fitted.

For further particulars see Rpt. 8 (Eq) attached.

It is now recommended that the condition of class regarding the anchor cable be deleted.

Appendix S.R.L. No. 17.

Nothing done at this time.

Conditions of Class.

Item regarding No. 6 D.B. tank, nothing done at this time.

The items now surveyed are detailed on this report. All were found or placed in good condition unless otherwise stated. I recommend, therefore, that this ship remain as classed ~~with~~ without fresh record of dry docking and without the special condition regarding the anchor cables, but subject to any other special conditions which may be attached to the ship's class being dealt with as previously recommended.

Appendix S.R.L. As previously noted.

(Where conditions of class are recommended to be retained, imposed, amended or deleted, particulars must be stated above and on the interim certificate.)

Date of Committee

LIVERPOOL

- 1 MAR 1966

R. Parker.

Minute

As now (Subject).

Surveyor to Lloyd's Register of Shipping

ALSO FOR

SPL FOR

TRO

SRL

POSTING

HEADER

CERT

Lloyd's Register Foundation

004489-004495-0191 1/2

action taken or recommended should be described fully under "defects & repairs". When any part has been subjected to pressure test this should be stated.

date of the next Special Survey. Where repairs have been effected or it is considered that re-examination or repairs should be made before that date the circumstances and

The condition of any item is to be described as "good" only when it has been examined, found or placed in good condition and is considered to be acceptable until the due



## Port Liverpool

Rpt. No.

167909

Fee Letter if diff. from Equipment Letter

## Equipment Letter

a 2" SQ

When anchors or cables are supplied or retested, the following particulars are required:

## ANCHORS

## CHAIN CABLES

[illegible]

**Yes**

Have test certificates of new or retested equipment (if now supplied) been checked and endorsed?

**Note:—**Where anchors or chain cables are lost or condemned and renewed or supplied the corresponding test certificates should be cancelled by the Surveyors.

*Surveyor to Lloyd's Register of Shipping*

R. Parker.

004489-004495-01912 2 1/2

31 MAR 1966

**Book**