

13 DEC 1965

Ship's name "INDIAN ENDEAVOUR"Port CALNo. 2030Class is subject toLast survey date 31.10.65.

No.6 D.B. tank top frames and reverse frames etc.,
being specially examined annually and dealt with
as necessary.

S.R.L. Appendix (as before ~~xxxxxxx~~)Nature of present survey (~~applied and in drydock~~)

Docking.

Wear and tear repairs.

Equipment:- 255 fathoms of chain cable found worn to and up
to 10.3% in area below Rule renewal diameter, recommended to

Recommendation be renewed.

SUBMITTED record of DS 10,65 be assigned,
subject as above, and to 255 fathoms of worn
chain cable on board being renewed at the earliest
opportunity, but further ACTION be DEFERRED
for Equipment.

DS 10,65 subject.

IN S.R.L. APPENDIX

Shell plate H.17 (s.s) set in



Lloyd's Register
Foundation