

004496-004501-0176

Empire Highway

Gs 66266. Pmc
don. 1293 Pmc

+ Lloyd's Pmc 11.42.

The Surveyors (G.) should state the required particulars regarding gas condenser circulating pumps which have been omitted from the report & also what alternative means if any are furnished for dealing with the exhaust steam from the Compressor Syries.

As it is not the Society's practice to mention proprietary articles in its publications the Surveyors should state whether "slag boiler" is a correct description of "Stillite" mentioned by A. 9/11/42. Also state whether they checked the spare gear.

Glasgow Committee.

REVIEWS

Rules

See Survey 17/11/42