

Memorandum.

TORSIONAL VIBRATION AUXILIARY MACHINERY

"JOAO ALVARES FAGUNDES"

Torsional vibration characteristics have not been submitted for the auxiliary machinery.

This machinery consists of 2 auxiliary engines, each driving a ~~X~~ 25 K.W. dynamo, and each engine is quite adequate to supply the whole of the current required for all essential services at sea.

It is a matter for consideration, therefore, whether the requirements in respect of torsional vibration calculations might be waived in the case of these engines and the Owners advised accordingly.

la.

11.9.45.

J.D.

Robt



© 2020

Lloyd's Register
Foundation

004502-004511-0181