

18816

23 MAR 1965

Ship's name

"KELANTAN"

Port

Sng.

No 18080Last survey date 23.2.65.

GB

Class is subject torudder and sternframe plating in way being
examined for possible damage (striking buoy) next drydocking.S.R.L. Appendix (~~XXXXXXXXXXXX~~ none)Surveys dueSPECIAL SURVEY (C) due 1,65. Postponement until 5,65
approved 11.12.65.Nature of present survey (afloat ~~and in drydock~~)Temporary repairs to fractured shell plate H.17 (p.s) and to
internal structure of all wing tanks (p & s) - see correspondence
regarding these items.Is interim certificate in order

Yes/No/None

Items outstanding if any for SS


ALL ITEMS.

SS proposed to be completed by

5,65.

RecommendationSUBMITTED ACTION be DEFERRED for S.S.
by 5,65, subject as above, and to shell
plate H.17 (p.s) and internal structure in
all wing tanks (p & s) being specially
examined and dealt with as necessary on
ship's arrival at Hirao, Japan, by 3,65.

SUBJECT

SID YKa March 14 to HIRAO *SHK*
23/3/65.Lloyd's Register
Foundation