

18816
COPY

Ship's name

"KELANTAN"

Port

Sng.

No 18080

Last survey date 23.2.65.

GB Class is subject to

rudder and sternframe plating in way being
examined for possible damage (striking buoy) next drydocking.

S.R.L. Appendix (as before or none)

Surveys due

SPECIAL SURVEY (C) due 1,65. Postponement until 5,65
approved 11.12.65.

Nature of present survey (afloat and in drydock)

Temporary repairs to fractured shell plate H.17 (p.s) and to
internal structure of all wing tanks (p & s) - see correspondence
regarding these items.

Is interim certificate in order

Yes/No/None

Items outstanding if any for SS

ALL ITEMS.


SS proposed to be completed by

5,65.

Recommendation

SUBMITTED ACTION be DEFERRED for S.S.
by 5,65, subject as above, and to shell
plate H.17 (p.s) and internal structure in
all wing tanks (p & s) being specially
examined and dealt with as necessary on
ship's arrival at Hirao, Japan, by 3,65.

SUBJECT



© 2020
28/3/65.
Lloyd's Register
Foundation