


COPY

# LLOYD'S REGISTER OF SHIPPING



Port of Piraeus,

28th November, 1960.

**This is to Certify that I have**

Surveyed the Machinery of the S.S. "MANDO" 772 tons gross of Piraeus  
whilst lying afloat & in drydock at Piraeus on the 23rd June,  
1960 & subsequently on account of Engine Survey, Conversion  
to Diesel & Docking Survey,

and that I will transmit to the Committee of Lloyd's Register of  
Shipping, London, a Report stating that all recommendations made by  
me in connection therewith have been carried out to my satisfaction; also  
that I will Recommend that in the case of this Vessel the following  
Survey Records be made in the Supplement to the Register Book

+LMC "Class contemplated"

and that her Machinery Classification Record be continued in the Book,  
subject to (1) the electrical installation being altered to  
rule requirements (2) efficient provision made for first  
charging air receivers at earliest opportunity and (3) bilge  
pumping being re-examined & dealt with as found necessary on  
vessel's return to Piraeus (about the end of  
Parts now examined: November, 1960), (Main engine not to be operated  
(C.S. Items only) continuously between 138 and 164 r.p.m.).

*S. Blakeman*

S. Blakeman

Engineer Surveyor to Lloyd's Register

## KEY TO ABBREVIATIONS

ABS	Auxiliary Boiler Survey
CS	Continuous Survey of Engines
DBS	Donkey Boiler Survey
ES	Engine Special Survey
MBS	Main Boiler Survey
MES	Modified Survey of Oil Engines
OF	Fitted for oil fuel (date) FP above 150°F.

SGS	Steam Generator Survey
SPS	Steampipe Survey
TS	Tailshaft Survey
TS(CL)	Tailshaft Survey—Continuous Liner
TSN	Tailshaft renewed
TS(OG)	Tailshaft Survey—Oil Gland

This Certificate is issued upon the terms of the Rules and Regulations of the Society, which provide that:—

"While the Committees of the Society use their best endeavours to ensure that the functions of the Society are properly executed, it is to be understood that neither the Society nor any Member of any of its Committees is under any circumstances whatever to be held responsible for any inaccuracy in any report or certificate issued by the Society or its Surveyors, or in any entry in the Register Book or other publication of the Society, or for any error of judgment, default or negligence of any of its Committees or any Member thereof, or the Surveyors, or other Officers or Agents of the Society."

(Cert. B.1.) 150m, 3,59 (MADE AND PRINTED IN ENGLAND.)

© 2020

Lloyd's Register  
Foundation

004534-004534