

EA

COPY

Ship's name

"STANLAND"

Port

GIB

No.

4670

Last survey date

16.3.63.

Class is subject to

indented side shell plating etc. in way of No.1 hold (p.s) and indented and set in shell plates F.7, G.7,8 & 14, J.8 (p.s) F.12 & 13, G.11, H.11, J.15 & 16 (s.s) all from forward being repaired at the next drydocking.

S.R.L. Appendix (as before or none)

Nature of present survey (afloat and in drydock)

Permanent/temporary repairs to H.W. damage.

Recommendation

SUBJECT as above and to repairs inway of after end of No.3A hatch (p.s) being specially examined and dealt with as necessary by 6,63.


As Now Subject.

IN S.R.L. APPENDIX

Indented shell plates (p & s).



© 2021



Lloyd's Register
Foundation

End. S.1

004564-004572-0112

(Where conditions of class are recommended to