

L'S NAME "MARACAY"

Report JCK., FLA. No. 1958

THICKNESSES OF PLATING ascertained by drilling, and comparison of same with the original thicknesses.

The thicknesses are in 100^{Ths.} of an inch.

TRAKE.	AMIDSHIP.					FORWARD.					AFT.					REMARKS.
	Original Thickness.	Thickness by drilling.		Diminution if any.		Original Thickness.	Thickness by drilling.		Diminution if any.		Original Thickness.	Thickness by drilling.		Diminution if any.		
		Port.	Std.	Port.	Std.		Port.	Std.	Port.	Std.		Port.	Std.	Port.	Std.	
DECK																
LOWER STRAKE																
DECK																
below G	48	46	45	2	3	41	38	36	3	5	41	36	37	5	4	(48) 48 (48) 48 32-43-28 ✓ ✓
" F	48	45	46	3	2	41	37	36	4	5	41	35	36	6	5	
" E	48	42	45	6	3	41	36	35	5	6	41	34	35	7	6	
" D	52	48	47	4	5	41	37	38	4	3	41	35	38	6	3	
" C			47	4	5	44	45	43	3	5	44	40	39	4	5	
" B	52		46	5	6	50	46	45	4	5	50	40	41	6	5	
" A	52	46	45	6	7	52	45	44	7	8	50	43	45	7	5	
Keel	77	73	74	4	3	68	65	64	3	4	68	66	63	2	5	
		✓	✓				✓	✓				✓	✓			

Decks Upper Deck Plating - 48
 Trunk Sides - 54
 Trunk Deck - 70

48 34

Drillings at ends to be made in the vicinity of the peak bulkheads.

2021 Lloyd's Register Foundation

A. Stewart

Decision +LMC 8-56
 TS (CL) (P&S) 8-5

MBS 8-56

004564-004572-0214