

s.s. "VRISSI"

With regard to the recommendation that the steam cylinder of the main circulating pump engine should be renewed by August 1952, Mr. Lentakis, a Representative of the Owners, states that the replacement is on board and will be fitted at the first possible opportunity.

11. 9. 52.



© 2021

Lloyd's Register
Foundation

004579-004590-0338