

COPY

LLOYD'S REGISTER OF SHIPPING

UNITED WITH THE BRITISH CORPORATION REGISTER

18 JUN 1951



Port Montreal, P.Q.

4th May, 1951

This is to Certify that

L. M. MATHERS

the undersigned Surveyor to this Society did at the request of

the Owners' Representative attend the Steel Single Screw Steamer "EIGIN", 1906 tons gross register of Montreal, on 5th April, 1951 and subsequent dates whilst she lay on the blocks in Kingston Dry Dock after Damage stated to have been sustained on account of Vessel's port side striking the Canadian Shipbuilding & Engineering Limited Coal Dock on 23rd January, 1951 while being towed by the tug "ASHTABULA" from the shipyard sheerleg berth to her winter mooring berth at the Canada Steamship Lines Shed at Kingston, Ont.

Upon examination, the undersigned

FOUND

Port Side counting from forward
Shell plate #10 set in.

Shell plate #11 set in.

Internally

5 side frames buckled.
3 side frames slightly buckled.
Bunker bulkhead wing plate buckled.

RECOMMENDED

To be cropped and part renewed and extended into #11.

To be cropped, part renewed and extended into #10.

Rubbing strap removed and new strap fitted in # strake.

To be removed, faired and replaced.

To be faired in place.

To be cropped and part renewed.

The above recommended permanent repairs having been satisfactorily carried out, the shell in way of repairs and the watertight bulkhead at shell were hose tested and found tight.

The above recommendations have been made with a view to the Vessel being restored as far as practicable, to the same condition as before the alleged casualty occurred.

L. M. Mathers

SURVEYOR TO LLOYD'S REGISTER

This Certificate is issued upon the terms of the Rules and Regulations of the Society, which provide that:—

While the Committees of the Society use their best endeavours to ensure that the functions of the Society are properly carried out, it is to be understood that neither the Society nor any Member of any of its Committees is under any circumstances to be held responsible for any inaccuracy in any report or certificate issued by the Society or its Surveyors, or in any entry in the Register Book or other publication of the Society, or for any error of judgment, default or negligence of any of its Committees or any Member thereof, or the Surveyors, or other Officers or Agents of the Society."