

Ship's Name SS/M- "GLENELG" LR 513194

Gross tons 2309

Is there a rpt. 9? Yes

Port Toronto

Rpt. No. 5308

No. of visits Two

First date 2.3.65

Last date 12.4.65

Interim Cert. issued
& copy herewith?

No

Damage rpt. issued
& copy herewith?

No

Last rpt. (H.Q. only) Tto. 574)

Date of
completing rpt. 10-6-65

Surveyed at, if different from Port above

Surveyed afloat
and/or in D.D.

Afloat

Last date of examination in D.D.

Has a Load Line
Survey been held?

Yes (Annual)

Freeboard Marks verified In Order

State which additional Rpt. 8 is attached: (Cont); (DR); (EQ); (Rig)

Survey fees \$36.00

Damage fee

Expenses \$10.00

U.S.S.A. 4.00

S.A. fee

R.F.B. No. Tto-3957

June 17, 1965

I/we have surveyed the above ship in accordance with the Rules for Lake Annual

Survey

Examined & Condition

Examined & Condition

Holds, incl. blkhd.,
inner btm. plating, etc

Good

Pumps & pumping arrgts.
outside mchy. space

Good

Bilges & ceiling

Good

Steering arrgts. incl. gear

Good

'Tween decks

Good

W.T. doors & sluice valves

Good

Deck &
deck erections

Good

*Ventilators

Good

Machinery space

Good

*Hatchways

Good

Under E. & B.

Good

*Casings & companionways

Good

Masts, rigging &
outfit

Good

*Superstructures

Good

Windlass &
hawse pipes

Good

Guard rails & freeing ports

Good

*Air & sounding
pipes

Good

Overboard discharges, ash
chutes & other shell openings

Good

Examined &
conditionTested &
conditionExamined &
conditionTested &
condition

Peaks

Good

No

Tankers

Cargo tanks

Cofferdams

Pump rooms

Side tanks in hold

Deep tanks

Has a grain survey
been held?

Yes

Has a damage survey been held? No

The items now surveyed are detailed on this report. All were found or placed in good order unless otherwise stated.

I/we recommend that this ship remain as classed with fresh record of Annual Survey. 4/65

(Where conditions of class are recommended to
be retained, imposed, amended or deleted, particulars
must be stated above and on the interim certificate.)

Date of Committee THURSDAY 22 JUL 1965

Minute

AS 4.65

MBS 4.65

Surveyor(s) to Lloyd's Register of Shipping

OR CHAIRMAN
CLASS. CTTER

004591-004595-0088

ALSO FOR

SPL FOR

TRO

SRL

POSTING

HEADER

CERT

unmended, should be
"defects & repairs".
s been subjected to
pressure test this should be stated.

made before that date the circumstances and

The condition of any item is to
as "good" only when it has been
found or placed in good condition and is
considered to be acceptable until the due

*These items to include their closing appliances