

COPY HAS BEEN SENT TO THE OSLO SURVEYORS

LLOYD'S REGISTER OF SHIPPING

BELONGS TO
ROTTERDAM REPORT NO:

51635

Part of ROTTERDAM

26th May, 1961

CLASS IS SUBJECT TO: *This is to Certify that I have*

Surveyed the Machinery of the *M.S. "FRANILLA", 10055 tons gross of*
Kristiansand, whilst lying afloat at this port on the 13th April, 1961
and subsequent dates for Damage Survey and Part Machinery.

and that I will transmit to the Committee of Lloyd's Register of
 Shipping, London, a Report stating that all recommendations made by
 me in connection therewith have been carried out to my satisfaction; also
 that I will **Recommend** that in the case of this Vessel the following
 Survey Records be made in the Supplement to the Register Book

and that her Machinery Classification Record be continued in the Book.
 subject to the after section of the main engine crankshaft being repaired
 as found necessary, the waterbox of the auxiliary condenser being renewed
 and Nos. 1, 2, 4, 5, 6 and 8 H.E. cylinder covers being specially examined
 before the vessel is recommissioned.

Parts now examined: (C.S. Items only)

The Surveyor states that this vessel has been
 and is to proceed to Valerik where it is stated she
 broken up, in view of this statement it is
 that the limit on all the above subject items
 ed to August, 1961 (2 months limit).

IS SUBMITTED that this vessel is
 subject as above but

E. M. Dudock
 Engineer Surveyor to Lloyd's Register.

KEY TO ABBREVIATIONS

ABS Auxiliary Boiler Survey
 CS Continuous Survey of Engines
 DBS Donkey Boiler Survey
 ES Engine Special Survey
 MBS Main Boiler Survey
 MES Modified Survey of Oil Engines
 OF Fitted for oil fuel (date) FP above 150°F.

SGS Steam Generator Survey
 SPS Steampipe Survey
 TS Tailshaft Survey
 TS(CL) Tailshaft Survey—Continuous Liner
 TSN Tailshaft renewed
 TS(OG) Tailshaft Survey—Oil Gland

This Certificate is issued upon the terms of the Rules and Regulations of the Society, which provide that:—

„While the Committees of the Society use their best endeavours to ensure that the functions of the Society are properly executed,
 is to be understood that neither the Society nor any Member of its Committees is under any circumstances whatever to be held
 responsible for any inaccuracy in any report or certificate issued by the Society or its Surveyors, or in any entry in the Register Book
 other publication of the Society, or for any error of judgment, default or negligence of any of its Committees or any Member thereof,
 the Surveyors, or other Officers or Agents of the Society.”