

b. Heavy weather on a voyage from Abadan to Rotterdam on the 8th July and subsequent

Received from Chief Ship Surveyor

22 DEC 1958

NAME "RANELLA" REPORT Ams. No. 22489

nding Conditions of Class: Subject to indented shell plates
K.8, L.9, M.9 (p.s. from aft) being dealt with as necessary
next drydocking.

ement of Certificate (As before ~~of None~~)

of Present Survey: (Afloat and in dry dock)

Docking: Heavy weather damage repairs.

endation: SUBMITTED record of 'DS 10,58' be assigned
as recommended, but without special condition.

DS 10,58 Without.

S.R.L. APPENDIX NOTE (AMENDED).

Shell plating (p & s) and keel plating aft indented.
(Ship is hogged about 7½.)



© 2021

Lloyd's Register
Foundation

004603-004611-0047