

9 MAR 1954

AFS.234

Rpt. C 11 (a).

## LLOYD'S REGISTER OF SHIPPING

UNITED WITH THE BRITISH CORPORATION REGISTER

## REPORT ON ANNUAL LOAD LINE SURVEY

Name of Ship **'BUSEN STAR'** Official Number **180878** Port of Registry **LONDON**  
 Place of Survey **FALMOUTH** Dates of Survey **23rd. and 26th, Feby, 5th, March, 1954** Date of last Load Line Survey **15th, July, 1952**

## PARTICULARS OF SURVEY

Items examined.	Condition in which found.	Repairs.	
		Necessary.	Date effected.
<b>HATCHWAYS, INCLUDING SMALL HATCHWAYS.</b>			
<b>1. Exposed on freeboard deck.</b>			
Coamings, their stays and stiffeners ... ..	GOOD ✓		
Beams ... ..	NONE		
Fore and afters ... ..	NONE		
*Covers <b>Watertight &amp; Oil Tight Steel</b> ...	GOOD ✓	Packing renewed. ✓	5th, March, 1954.
*Tarpaulins ... .. (State number per hatchway)	NONE		
*Cleats and battens ... ..	NONE		
Lashings and their fittings ... <b>TOGGLES</b> ...	GOOD ✓	Toggles overhauled. ✓	5th, March, 1954.
Wedges ... .. (Is supply, including spares, adequate ?)	NONE		
<b>2. Exposed on superstructure decks, including raised quarter decks.</b>			
Coamings, their stays and stiffeners ... ..	GOOD ✓		
Beams ... ..	NONE		
Fore and afters ... ..	NONE		
*Covers ... <b>Watertight steel</b> ... ..	GOOD ✓		
*Tarpaulins ... .. (State number per hatchway)	NONE		
*Cleats and battens ... ..	NONE		
Lashings and their fittings ... <b>Toggles</b> ...	GOOD ✓	Toggles freed. ✓	5th, March, 1954.
Wedges ... .. (Is supply, including spares, adequate ?)	NONE		
<b>3. Within superstructures not intact or not protected by Class I closing appliances.</b>			
Coamings ... ..	GOOD ✓		
Beams ... ..	NONE		
Fore and afters ... ..	NONE		
Covers ... <b>Watertight steel</b> ... ..	GOOD ✓		
Tarpaulins ... .. (State number per hatchway)	NONE		
Cleats and Battens ... <b>Toggles</b> ... ..	GOOD ✓	2 Toggles Freed. ✓	5th, March, 1954.
Wedges ... .. (Is supply, including spares, adequate ?)	NONE		
<b>VENTILATORS IN EXPOSED POSITIONS.</b>			
<b>4. To spaces below freeboard deck.</b>			
Coamings, their supports and deck connections ... ..	GOOD ✓		
Closing arrangements ... ..	GOOD ✓		
<b>5. To spaces below decks of superstructure which are intact or closed by Class I appliances.</b>			
Coamings, their supports and deck connections ... ..	GOOD ✓		
Closing arrangements ... ..	GOOD ✓	Missing Plugs and covers renewed. ✓	5th, March, 1954.
<b>AIR PIPES.</b>			
<b>6. Exposed on freeboard and superstructure decks.</b>			
Closing arrangements ... ..	GOOD ✓	3 Covers renewed. ✓ Hinging tops freed. ✓	5th, March, 1954.
<b>7. Within partially enclosed superstructures.</b>			
Closing arrangements ... ..	NONE		
<b>MACHINERY CASINGS.</b>			
<b>8. Casing Top.</b>			
Fiddle openings, their covers and fastenings ... ..	GOOD ✓		
Skylights, their fastenings, covers and lashings ... ..	GOOD ✓	6 Glasses renewed. ✓	5th, March, 1954.
<b>9. Exposed on freeboard and raised quarter decks.</b>			
Doors and fastenings ... ..	NONE		
<b>10. Exposed on superstructure decks other than raised quarter decks.</b>			
Doors and fastenings ... ..	GOOD ✓	Locks repaired. ✓	5th, March, 1954.
<b>11. Within partially enclosed superstructures.</b>			
Doors and fastenings ... ..	NONE		
<b>12. FLUSH BUNKER SCUTTLES and chain attachments</b> ...			
	NONE		
<b>13. COMPANIONWAYS, including deckhouses enclosing ladderways.</b>			
Doors, fastenings, covers ... ..	GOOD ✓	Door locks renewed. ✓	5th, March, 1954.

\* Tarpaulins, battens, covers, etc., to be examined in place as well as separately (see Ministry of Transport Circular 1687, paragraph 117 (f)).

Items examined.	Condition in which found.	Repairs.	
		Necessary.	Date effected.
<b>14. CLOSING APPLIANCES FOR OPENINGS IN SUPER-STRUCTURE BULKHEADS.</b>			
Forecastle ... ..	GOOD ✓		
Bridge, fore end ... ..	GOOD ✓	Toggles freed. ✓	5th, March, 1954. ✓
Bridge, after end ... ..	GOOD ✓		
Poop ... ..	GOOD ✓	Toggles freed. ✓	5th, March, 1954. ✓
<b>15. GANGWAY, CARGO AND COALING PORTS.</b>			
In ship's side and superstructures ... ..	NONE		
<b>16. SCUPPERS AND SANITARY DISCHARGE PIPES.</b>			
Valves ... ..	GOOD ✓	2 Leathers renewed.	5th, March, 1954.
<b>17. SIDE SCUTTLES AND DEADLIGHTS ... ..</b>			
	GOOD ✓		
<b>18. GUARD RAILS ... ..</b>			
	GOOD ✓		
<b>19. PROTECTION AND ACCESS TO CREW'S QUARTERS.</b>			
Gangways ... ..	GOOD ✓		
<b>20. LIFELINES (fittings and material) ... ..</b>			
	NONE		
<b>21. FREEING PORTS.</b>			
Shutters ... ..	NONE		
Protection bars ... ..	NONE		
<b>22. <del>TANKER</del> TANKER OR SPECIAL STEAMER LOAD LINES.</b>			
Fittings or appliances ... ..	GOOD ✓		
<b>23. ITEMS NOT INCLUDED IN THE FOREGOING.</b>			
<b>24. LOAD LINE MARKS ... ..</b>			
	VERIFIED ✓ 23.2.54.		

**Certificate A. To be signed by Surveyor in respect of a partial or complete survey.**

I have surveyed the ship named at the head hereof, to the extent indicated below, in accordance with the instructions contained in Ministry of Transport Circular 1687, and the requisite details of the survey have been entered herein.

Index Nos. of items examined.† († Insert "all" in case of a complete survey.)	Signature of Surveyor.	Place.	Date.
ALL	A.M. JENKINS ✓	FALMOUTH	5th, March, 1954

**Certificate B. To be signed by Surveyor completing the survey.**

I am satisfied

(i) that the fittings and appliances for the protection of openings, the guard rails, the freeing ports and the means of access to the crew's quarters have been maintained on the ship in as effective a condition as they were in when the certificate was issued; and

(ii) that no material alterations have taken place in the hull or superstructures of the ship which affect the positions of the load lines.

I have endorsed the Load Line Certificate and the certified copy as follows:—

Signature of Surveyor A.M. JENKINS ✓ Place FALMOUTH Date 5th, March, 1954

Signature Alex M. Jenkins ✓

Date 8th, March, 1954.

Fee £18.15. 0.

Number of Visits 3

Particulars of any change from the conditions given on the Load Line Certificate or on Form C 11 should be reported on Form C 11 (contd.) and attached to the Form C 11 on the Ship, a copy being forwarded to the Freeboard Department.

Surveyors should note that there is only one valid certificate, and the above endorsement should be made thereon. No entry should be made on a certified copy of the certificate unless the original certificate has been produced to and endorsed by the Surveyor.



© 2021

Lloyd's Register Foundation

10 MAR 1954