

"BIRCHGROVE PARK"

It is submitted Mr. Fielden be informed that it is noted from the Technical Press that this ship sank in heavy weather off Sydney on August 2nd last, and he be requested to keep this Office advised of any action which may be taken by the Australian Authorities to investigate this casualty by the holding of an inquiry. He should inform this Office of any matters which he is able to ascertain will be likely to arise during the course of any inquiry and which will affect the Society's interests,

In this connection he should be informed that it is noted from Sydney Report 8 No. 29236 that "owing to reduced thickness of couplings it is recommended that the rudder main piece and stock be renewed by the next Special Survey.....", and he should be asked to amplify these remarks as fully as possible by quoting the actual measurements taken at the Survey and giving the Surveyor's comments as to the reason for the reduction in thickness, i.e. whether <sup>due</sup> to pitting or to general corrosion.

*Wm*  
21.9.56.



© 2020  
Lloyd's Register  
Foundation

004612-004620-0161

INFO  
Sydney  
Park, 4  
Ltd.,  
to Sy  
bank o  
her. 3  
ed, nin  
Sydney  
ne Tho  
rivor in  
ever s  
started  
ark di  
ney H  
r at So  
Gosling  
and co  
tions.  
lly, fas  
lamp.  
elligible  
vo wor  
stowag  
n 10 se  
gone a  
and b  
fast th  
ic." Th  
eported  
heavy  
npany.  
Sydney,  
at eight  
on the  
was on  
to Syd  
r there.  
he cre  
lifeboa  
that th  
list du  
e impo  
Captain  
ng the  
Sydney,  
Park fo  
her c  
eas.—E