

1,53

5 E

29 AUG 1956

ived by Chief Engineer Surveyor

Received from Chief Engineer Surveyor

IP'S NAME "BIRCHGROVE PARK."

REPORT Syd.

No. 29236

The remarks of the Chief Engineer Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/52.)

ure of Survey

DAMAGE & WEAR AND TEAR.

Docking. Screw shaft seen. The liner found worn and the  
shaft renewed.

It is submitted the vessel is eligible to remain as classed, with  
record of Survey S. (N) CL 7.56. as recommended.

*[Handwritten signature]*



© 2020  
27.8.56.

Lloyd's Register  
Foundation

Decision

004612-004620-0170

5N756

*[Handwritten signature]*  
Engineer Surveyor to Lloyd's