

1,61
 is subject to

the diesel auxiliary engine being repaired before the end of June, 1961.

ceived by Chief Engineer Surveyor.....

Received from Chief Engineer Surveyor..... 13 SEP 1961

SHIP'S NAME "RIVER FITZROY" REPORT N.S.W. No. 7886

ES due 3.62 - now commenced.

MBS due 8.61 - now commenced.

Repairs

Considerable deposits found in tubes of both boilers and some pitting at tube ends.

Vessel now laid up and Surveyor recommends the tubes of both boilers be specially examined before completion of present survey.

IT IS SUBMITTED that the vessel will be eligible for the record ES with date and MBS 8.61 when the survey has been completed, subject as above and as now recommended.

13.9.61

To complete ES

See Form 10E

To complete MBS

Deal with subject of class.
 Adjust safety valves of Port boiler.

© 2020

Lloyd's Register
 Foundation

004621-004629-0125