

COPY

LLOYD'S REGISTER OF SHIPPING

71, Fenchurch Street, London, E.C.3

Telegraphic Address { Inland: Committee, London, Telex
Overseas: Committee, London, E.C.3

Telephone: 01-709 9166
Telex No.: 24305

Your Ref: I.McL.O/DR.

24th November, 1967.

C.
RNC/MRW.

Dear Sirs,

Steamer "SYROS"

The remarks contained in your letter of 20th instant have been under the consideration of the Committee here today.

As a result, they have asked me to point out that in view of ~~passed~~ experience with the "Liberty" type of screwshaft, it is not their practice to agree to a postponement of six months for such a survey.

If this ship is to remain in class, you must, therefore, ask the Owners to submit a better proposal for this shaft to be examined at a much earlier date.

At the same time, the Owners should state what arrangements they propose making to hold the Main Boiler Survey that fell due in July, 1967, as well as the renewal of the steam windlass cylinder block which was recommended to be done before the end of July last.

Yours faithfully,

Classification Manager.
Messrs. Hunter Shipping Co. Ltd.,
87, Bishopsgate,
LONDON, E.C.2.



© 2020

Lloyd's Register
Foundation

004630-004634-0084