

COPY

LLOYD'S REGISTER OF SHIPPING^{DNS}

71, Fenchurch Street, London, E.C.3

Telegraphic { Inland: Committee, London, Telex
Address { Overseas: Committee, London E.C.3

Telephone: ROYal 9166
Telex No.: 24305

TELEX MESSAGE TO SLUITER CARE OF SHIPYARD CURACAO

TELEX NO. CU~~2~~ 17 (3 1 67)

PATELLA REURTELEX THREE LENGTHS OF CHAIN CABLE SHOULD BE TRANSFERRED FROM STARBOARD SIDE AND CONNECTED TO THE THREE LENGTHS REPLACEMENT CABLE AVAILABLE TO WHICH SPARE BOWER ANCHOR SHOULD BE FITTED THUS HAVING TWO WORKING BOWER ANCHORS WITH SEVEN AND SIX LENGTHS OF CHAIN CABLE RESPECTIVELY.

COMMITTEE.



© 2020

Lloyd's Register
Foundation

004630-004634-0280